


Art.no 481-10


FIRST USE

STEP 1.



ON : Press 3 seconds


STEP 2.



- ON 1 : Press 1 time 70Lm steady ON / motion sensor off
- ON 2 : Press +1 time 70Lm steady ON / motion sensor ON (p 3)
- ON 3 : Press +1 time 70Lm steady OFF / motion sensor ON (p 3)




OFF : Press 3 seconds












Ready after
36 h in the sun

BATTERY REPLACEMENT





STAR[®]
TRADING
STAR STREET 1
512 50 SVENLJUNGA
SWEDEN
www.startrading.com



Art No: 481-10


70 LUMEN CONSTANT LIGHT

MOTION SENSOR 500 LUMEN FOR 25 SEK



FUNCTION

- ON 1 : Press 1 time 70Lm steady ON / motion sensor off
- ON 2 : Press +1 time 70Lm steady ON / motion sensor ON (500Lm for 25 sec)
- ON 3 : Press +1 time 70Lm steady OFF / motion sensor ON (500Lm for 25 sec)
- OFF: Press 3 seconds



STAR[®]
TRADING
STAR STREET 1
512 50 SVENLJUNGA
SWEDEN
www.startrading.com